




START CONNECTIONS




RUN CONNECTIONS



THREE PHASE – 6 LEAD
PART WINDING START



VIEW OF TERMINAL END

				TOLERANCES UNLESS SPECIFIED			DRAWN KL 12-29-2003					
				DEC.	INCHES		CHK ML 12-30-2003					
				.X	± -		APPD EAB 01-02-2004					
				.XX	± -		SCALE 1=1					
				.XXX	± -		REF					
				.XXXX	± -	TITLE EXTERNAL CONNECTION DIAGRAM 3Ø - PART WINDING START			FMF MU49430			
NO.	REVISION		BY & DATE	CHK	ANG	± -	FINISH			PREV		
THIS DRAWING IN DESIGN AND DETAIL IS OUR PROPERTY AND MUST NOT BE USED EXCEPT IN CONNECTION WITH OUR WORK ALL RIGHTS OF DESIGN AND INVENTION ARE RESERVED THIS IS AN ELECTRONICALLY GENERATED DOCUMENT - DO NOT SCALE THIS PRINT				RFP 01-02-2004		CAD FILE EE7341-LN		SIZE	DRAWING NO.	PAGE	OF	REV.
				DIST WA-LB				A	EE7341-LN			