



# **BALDOR® • RELIANCE**

## **Product Information Packet**

# **248-151AS**

**24P GRNDR PIVOTAL SPEC 35P486Z331**

Copyright © All product information within this document is subject to Baldor Electric Company copyright © protection, unless otherwise noted.

Part Detail							
Revision:	AF	Status:	PRD/A	Change #:		Proprietary:	No
Type:		Prod. Type:		Elec. Spec:		CD Diagram:	
Enclosure:	TEFC	Mfg Plant:		Mech. Spec:	B2-8	Layout:	
Frame:	143	Mounting:	F1	Poles:		Created Date:	
Base:	RG	Rotation:		Insulation:		Eff. Date:	01-13-2011
Field Type:		Literature:		Elec. Diagram:		Replaced By:	
Nameplate NP0234							
CAT.NO.	248-151AS						
HP	1 1/2	VOLTS			115		
PHASE	1	AMPS			15		
HZ	60	RPM			3600		
SER.NO							
SPEC.	B2-8A						

Parts List		
Part Number	Description	Quantity
G8BA3000A15	SPL BASE 528C -- 8" & 10" GRINDERS,W/FUS	1.000 EA
10XN2520A12	O1/4-20X 3/4 HEX HEAD CAP	4.000 EA
HW1001A25	LOCKWASHER 1/4, ZINC PLT .493 OD, .255 I	4.000 EA
G8CB4500A02	G8-272 BASE COVER,STPD X PLATED	1.000 EA
51XW0832A07	8-32 X .44, TAPTITE II, HEX WSHR SLTD SE	2.000 EA
WD4102A15	HEYCO #1200 STRAIN RELIEF	1.000 EA
MK6000A04	NEO TUBE.313XIDX.031X3"LG X	1.000 FT
WD4007A11	SC4063, #9815 KNOB/DIAL KIT (SMALL)	1.000 EA
12XN1032A12	SCREW 10-32 X 3/4 HEX HD SLTD	2.000 EA
HW1000A10	#10 FLAT WASHER (SAE)	2.000 EA
XY1032A02	10-32 HEX NUT DIRECTIONAL SERRATION	2.000 EA
WD4004A01	FUSE HOLDER BUSMANN HKP	1.000 EA
SP9002SP	SWITCH 7402K4 (C-H)	1.000 EA
HA6219A01	BELT GRNDR ADAPTOR, MACH	1.000 EA
91XN3816A16	3/8-16X1 HEX SOC CNTRSK	4.000 EA
HA6220A01	PIVOTAL BRACKET, MACH	1.000 EA
HA6218A01	MOUNTING BRACKET, MACH	1.000 EA
91XN3816A16	3/8-16X1 HEX SOC CNTRSK	4.000 EA
RB4011A01	BEARING RETAINER, STAMPED (PLATED)	1.000 EA
10XN2520A08	1/4-20X1/2 HEX HEAD CAP	3.000 EA
HW1001A25	LOCKWASHER 1/4, ZINC PLT .493 OD, .255 I	3.000 EA
HA6222	PULL KNOB RETAINER PLATE	1.000 EA
53XN1032A06	10-32X3/8 PAN HD SLTD SER	2.000 EA
HA6068A02	BRACKET, TOOL REST MACH	1.000 EA

Parts List (continued)		
Part Number	Description	Quantity
10XN3118A14	5/16-18 X 7/8 HEX HEAD CAP	1.000 EA
HW1000A31	5/16 SAE FL WSHR NARROW, ID=.344, OD=.62	1.000 EA
HW1001A31	LOCKWASHER 5/16, ZINC PLT.591 OD, .319 I	1.000 EA
G8AP1003A01SP	TOOL REST	1.000 EA
10XN3816A24	3/8-16 X 1 1/2 HEX HD CAP SCREW	1.000 EA
HW1001A38	LOCKWASHER 3/8, ZINC PLT .688 OD, .382 I	1.000 EA
XY3816A12	3/8-16 FINISHED NUT	1.000 EA
HW1000A38	WASHER, 3/8" FLAT, SAE Z/P	2.000 EA
B2AP1005A02	PLATEN FOR BELT GRINDER WELKER	1.000 EA
12XN0832A08	8-32 X 1/2 HEX HD	2.000 EA
HW1001A08	WASHER, #8 SPLT LK, ZN	2.000 EA
B2FH2806A01SP	CONTACT WHEEL GUARD	1.000 EA
10XN2520A26	1/4-20X 1 5/8 HEX HD	2.000 EA
HW1001A25	LOCKWASHER 1/4, ZINC PLT .493 OD, .255 I	2.000 EA
B2AP5002A01	TRACK ARM & SHAFT ASSY	1.000 EA
B2FH2801A01SP	GRINDER GUARD, MACH	1.000 EA
10XN2520A12	O1/4-20X 3/4 HEX HEAD CAP	2.000 EA
HW1001A25	LOCKWASHER 1/4, ZINC PLT .493 OD, .255 I	2.000 EA
HW1000A25	1/4 SAE FLAT WASHER (FS)	2.000 EA
B2AP3003A01SP	IDLER WHEEL -- BELT GRINDER	1.000 EA
HW5000A51	N5000-156 RETAINER RING (F/S)	2.000 EA
BG6203E03	6203 D.SL,C3,POLYREX EM	2.000 EA
HW5010A32	RET RING 5100-66 (WALDES)	1.000 EA
B2AP1000A01	LATCH, IDLER ARM -- MACH	1.000 EA

Parts List (continued)		
Part Number	Description	Quantity
HA7001A01SP	TORSION SPRING,4.5" FREE-LENGTH, .855 I.	1.000 EA
HA7002A01	TORSION SPRING, .843 FREELENGTH, .437 I.	1.000 EA
10XN3816A20	3/8-16X1 1/4 HEX HD CAP	1.000 EA
80XN2520A06	1/4-20 X 3/8 SET SCREW	1.000 EA
HA5000A01	KNOB AND STUD ASSY	1.000 EA
B2AP5001A01SP	CONTACT WHEEL ASSY WITH RUBBER THREAD	1.000 EA
HW1000A75	WASHER, 3/4 FLAT, ZN	2.000 EA
XY7510A12SP	3/4-10 NUT R.H. HEX (NC) ZINC PLATED	1.000 EA
B2AP3005A01	ABRASIVE BELT, 2" X 48" ZGR300501	1.000 EA
B2FH2810A01SP	GUARD (HALF) MACHINED, USE W/B2FH2811A01	1.000 EA
B2FH2810A01SP	GUARD (HALF) MACHINED, USE W/B2FH2810A01	1.000 EA
51XN1032A12	10-32 X 0.750 HX WS SL SR	3.000 EA
HW1023A10	WASHER,#10 INT/EX TH LK, ZN X TDR#2	3.000 EA
XY1032A02	10-32 HEX NUT DIRECTIONAL SERRATION	3.000 EA
93XN1032A12	10-32X3/4 SHOULDER/TYPE T TDR 1	2.000 EA
HW1003A10	WASHER, #10 EX TH LK, ZN X	2.000 EA
B2FH2808A01SP	GUARD COVER, MACH	1.000 EA
93XN1032A12	10-32X3/4 SHOULDER/TYPE T TDR 1	2.000 EA
HW1003A10	WASHER, #10 EX TH LK, ZN X	2.000 EA
B2FH2809A01SP	GUARD COVER, MACH	1.000 EA
93XN1032A08	10-32X1/2 SHOULDER/TYPE T	1.000 EA
HA6223	LOCKING PIN (WELKER)	1.000 EA
HW2404A01	KNOB, #597 DIMCO-GRAY	1.000 EA
HA7005A02	C0360-032-0940S,ASSC.SPRGSTLS.STEEL,.94	1.000 EA

Parts List (continued)		
Part Number	Description	Quantity
WD2502A12	MDA 25A, BUSSMAN FUSE OR LITTLEFUSE #	1.000 EA
LD5024A02	14-3 COND. TYPE CORD W/ MOLDED PLUG 300V	1.000 EA
CN3000A18SP	SC3296,#9433 KBIC 125 SPEED CONTROL	1.000 EA
WD3007A12	.006 OHM RES,SC3308,#9850SEND BULK PKG.	1.000 EA
35P486Z331	1.5HP,3600RPM,DC,143TCYZ,3524P,TEFC,F1,N	1.000 EA
LB5003A01	TAG, CONNECTION	1.000 EA
MG1000G01	400-0116 BATTLESHIP GRAY LACQUER (55G)	0.017 GA
LB1119	WARNING LABEL	1.000 EA
LB1125C01	STD (STOCK) CARTON LABEL BALDOR WITH FLA	1.000 EA
LB1014	WARNING LABEL, FOR BELT GRINDERS	1.000 EA
NP0234	NP- 8" GR, BLANK UL W/O CSA	1.000 EA
85XU0407A04	#4-7 X 1/4 DRIVE PIN	2.000 EA
B2PA1001	PACKAGING GROUP	1.000 EA
MN902	MANUAL FOR BELT GRINDERS	1.000 EA

Accessories		
Part Number	Description	Multiplier
GA16	PEDESTAL INDUSTRIAL, CAST IRON 6" - 10"	A8
GA14	PEDESTAL FABRICATED STEEL W/SHELVES	A8
GA20	PEDESTAL INDUSTRIAL, CAST IRON 8"-14"	A8
GA20E	PEDESTAL LIGHT INDUSTRIAL,STEEL	A8
AB248	2' X 48' 80 GRIT GRINDER BELT	A8

