



SECTION "A-A"

17	ENDBELL ASSEMBLY
16	SHIM WASHER .030
15	SHIM WASHER .015
14	LOAD SPRING
13	CONDUIT BOX COVER GASKET
12	CONDUIT BOX GASKET
11	CONDUIT BOX COVER
10	CONDUIT BOX
9	HEX NUT KEPS 10-32
8	T-BOLT 10-32
7	HEX NUT KEPS 8-32
6	BRUSH CAP
5	BRUSH ASSEMBLY
4	TFS 8-32 X .38 PP PO
3	ENDBELL MACHINED
2	ARMATURE/SHAFT ASSEMBLY
1	MAGNET/FRAME ASSEMBLY
ITEM	DESCRIPTION

		TOLERANCES UNLESS SPECIFIED		LEESON	ELECTRIC MOTORS GEARMOTORS AND DRIVES	DRAWN	IPG 5/17/07					
		DEC.	INCHES			CHK	SAD 5/17/07					
01	REVISED ARMATURE AND MAGNET LOCATIONS. ECR90161	RPB	11/1/07	SJB	.XX	±.01	TITLE	GENERAL ASSEMBLY	SCALE	3=4		
00	RELEASED: REF. M1041224.00, 31 TT FR CONSOLIDATION, IPG 5/17/07	SAD	.XXX	±.005	MAT'L		31 FRAME DC		REF	M1041224.00		
ECN 07-1634		CHK	.XXX	±.005	FINISH		M120046.00		FMF	M120046.00		
NO.	REVISION	BY & DATE	CHK	ANG	±1/2"	CAD FILE		M1041244	SIZE	DRAWING NO.	REV.	
THIS DRAWING IN DESIGN AND DETAIL IS OUR PROPERTY AND MUST NOT BE USED EXCEPT IN CONNECTION WITH OUR WORK ALL RIGHTS OF DESIGN AND INVENTION ARE RESERVED THIS IS AN ELECTRONICALLY GENERATED DOCUMENT - DO NOT SCALE THIS PRINT								RFP	B		M1041244.00	01

```
ERROR: undefined
OFFENDING COMMAND: 1
```

```
STACK:
```

```
/newpath
/N
-dictionary-
/Pscript_WinNT_Compat
-dictionary-
```